

Progress Photo Examples:



Photo 1: Wet basin looking south west at its initial grading



Photo 2: Infiltration basin looking east after undercutting poor soils and replacing with granular soils meeting infiltration requirements.



Photo 3: Infiltration basin looking north underdrain configuration



Photo 4: Bioretention basin looking northwest engineered soil prior to final grading and restoration



Photo 5: Infiltration basin looking north deep tilled native soil layer with under drain exposed as engineer soil placement commencing



Photo 6: Engineered soil.



Photo 7: Wet basin looking south west fully vegetated establishment



Photo 8: Infiltration basin looking north fully completed after vegetation establishment